


## **U012**Mounting Instructions

D



## PARTS LIST

- A. Recessing Box
- B. Dryer
- C. Face Plate
- D. Fastner

## **INSTRUCTIONS**

- 1. Provide a rough wall opening 11 1/4"W x 15 3/4"H x 3 1/2"D
- 2. Select the proper knockout location for each application.
- 3. Secure box in wall opening with proper fasteners
- 4. Have qualified, licensed electrician run electrical connection through knockout location
- 5. Secure base to recessing box and connect power to dryer
- 6. Test dryer operation
- 7. Secure dryer cover and test dryer again
- 8. Secure face plate